

Roof Safety Report

**Victoria Gardens Shopping
Centre, VIC 3121**

Prepared By: Safemaster Safety Products
Date: 25-06-2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Victoria Gardens Shopping Centre in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Victoria Gardens Shopping Centre and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Brandon Vitek (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Brandon Vitek (Height Safety Inspector)

Roof Safety Report for
Victoria Gardens Shopping Centre, VIC 3121

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Victoria Gardens Shopping Centre	Victoria Gardens Shopping Centre, VIC 3121	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

25-06-2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Victoria Gardens Shopping Centre buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	EWP Access Only Sign	Safemaster	L1	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
2	EWP Access Only Sign	Safemaster	L2	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
3	Handrail (AI)	Safemaster	L3	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
4	Access Sign	Safemaster	L3 Access Door	Unknown	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
5	Low Pro Anchor Point	Safemaster	L3	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
6	Low Pro Anchor Point	Safemaster	L3	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
7	Access Ladder (AI)	Unknown	L4	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
8	Access Ladder (AI)	Safemaster	L4	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
9	Handrail (AI)	Safemaster	L4	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
10	Surfacemount Anchor Point	CARE	L5	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
11	Surfacemount Anchor Point	CARE	L5	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Surfacemount Anchor Point	CARE	L5	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
13	Surfacemount Anchor Point	CARE	L5	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
14	Surfacemount Anchor Point	CARE	L5	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
15	Surfacemount Anchor Point	CARE	L5	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
16	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
17	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
18	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
19	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
20	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
21	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
22	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
24	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
25	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
26	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
27	Brittle Roof Sign	Safemaster	L5	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
28	Step Over (AI)	Safemaster	L7	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
29	Access Ladder (AI)	Safemaster	L8	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
30	Handrail (AI)	Safemaster	L8	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
31	Low Pro Anchor Point	Safemaster	L9	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
32	Low Pro Anchor Point	Safemaster	L9	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
33	Low Pro Anchor Point	Safemaster	L9	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Low Pro Anchor Point	Safemaster	L9	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
35	Low Pro Anchor Point	Safemaster	L9	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
36	Low Pro Anchor Point	Safemaster	L9	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
37	Low Pro Anchor Point	Safemaster	L9	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
38	Low Pro Anchor Point	Safemaster	L9	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
39	Access Ladder (Al)	Safemaster	L10	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
40	Handrail (Al)	Safemaster	L10	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
41	Access Ladder (Al)	Safemaster	L11	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
42	Handrail (Al)	Safemaster	L11	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
43	Access Ladder (Al)	Unknown	L11	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
44	Access Ladder (Al)	Unknown	L12	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Guardrail (AI)	Unknown	L12	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
46	Brittle Roof Sign	Safemaster	L13	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
47	Brittle Roof Sign	Safemaster	L13	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
48	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
49	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
50	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
51	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
52	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
53	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
54	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
55	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
57	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
58	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
59	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
60	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
61	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
62	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
63	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
64	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
65	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
66	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
68	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
69	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
70	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
71	Low Pro Anchor Point	Safemaster	L14	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
72	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
73	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
74	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
75	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
76	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
77	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
79	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
80	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
81	Brittle Roof Sign	Safemaster	L15	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
82	Access Ladder (AI)	Unknown	L16	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
83	Guardrail (AI)	Unknown	L16	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
84	Low Pro Anchor Point	Safemaster	L17	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
85	Low Pro Anchor Point	Safemaster	L17	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
86	Low Pro Anchor Point	Safemaster	L18	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
87	Low Pro Anchor Point	Safemaster	L18	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
88	Guardrail (AI)	Unknown	L18	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
90	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
91	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
92	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
93	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
94	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
95	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
96	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
97	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
98	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
99	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
101	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
102	Surfacemount Anchor Point	CARE	L19-L20	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
103	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
104	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
105	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
106	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
107	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
108	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
109	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
110	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
112	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
113	Surfacemount Anchor Point	Safemaster	L21	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
114	Surfacemount Anchor Point	Safemaster	L21	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
115	Surfacemount Anchor Point	Safemaster	L21	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
116	Access Ladder (Al)	Safemaster	L22	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
117	Handrail (Al)	Safemaster	L22	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
118	Access Sign	Safemaster	L23	Unknown	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
119	Access Ladder (Al)	Unknown	L23	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
120	Step Over (Al)	Safemaster	L24	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
121	Step Over (Al)	Safemaster	L24	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Step Over (AI)	Safemaster	L25	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
123	Step Over (AI)	Safemaster	L25	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
124	Access Ladder (AI)	Unknown	L26	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
125	Step Over (AI)	Safemaster	L27	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
126	Step Over (AI)	Safemaster	L27	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
127	Handrail (AI)	Safemaster	L29	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
128	Access Ladder (AI)	Safemaster	L30	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
129	Handrail (AI)	Safemaster	L30	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
130	Handrail (AI)	Safemaster	L31	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
131	Handrail (AI)	Safemaster	L32	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
132	Handrail (AI)	Safemaster	L33	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Step Over (AI)	Safemaster	L34	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
134	Access Ladder (AI)	Unknown	L34	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
135	Guardrail (AI)	Unknown	L34	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
136	Handrail (AI)	Safemaster	L35	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
137	Access Ladder (AI)	Safemaster	L35	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
138	Handrail (AI)	Safemaster	L35	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
139	Handrail (AI)	Safemaster	L35	11/01/2019	25/06/2019	25/06/2020	AS 1657:2018	Pass	
140	Roof Access Hatch	Unknown	L35	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
141	Surfacemount Anchor Point	CARE	L35	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
142	Surfacemount Anchor Point	CARE	L36	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
143	Guardrail (AI)	Unknown	L36	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
145	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
146	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
147	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
148	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
149	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
150	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
151	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
152	Low Pro Anchor Point	Safemaster	L37	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
153	Access Ladder (Al)	Unknown	L38	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
154	EWP Access Only Sign	Safemaster	L39	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Guardrail (AI)	Unknown	L40	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
156	Access Ladder (AI)	Safemaster	L41	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
157	Anchor Point Strop	Safemaster	L41	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
158	Low Pro Anchor Point	Safemaster	L41	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
159	Low Pro Anchor Point	Safemaster	L41	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
160	Low Pro Anchor Point	Safemaster	L41	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
161	Low Pro Anchor Point	Safemaster	L41	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
162	Low Pro Anchor Point	Safemaster	L41	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
163	Surfacemount Anchor Point	Safemaster	L42	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
164	Surfacemount Anchor Point	Safemaster	L42	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
165	Surfacemount Anchor Point	Safemaster	L42	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Surfacemount Anchor Point	Safemaster	L42	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
167	Access Ladder (AI)	Safemaster	L43	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
168	Handrail (AI)	Safemaster	L43	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
169	Step Over (AI)	Safemaster	L43	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
170	Low Pro Anchor Point	Safemaster	L44	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
171	Low Pro Anchor Point	Safemaster	L44	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
172	Access Ladder (AI)	Safemaster	L46	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
173	Handrail (AI)	Safemaster	L46	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
174	Access Ladder (AI)	Safemaster	L46	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
175	Access Ladder (AI)	Safemaster	L47	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
176	Handrail (AI)	Safemaster	L47	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
177	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
178	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
179	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
180	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
181	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
182	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
183	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
184	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
185	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
186	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
187	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
188	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
189	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
190	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
191	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
192	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
193	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
194	Low Pro Anchor Point	Safemaster	L48	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
195	Guardrail (AI)	Unknown	L49	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
196	Low Head Room Sign	Safemaster	L50	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
197	Low Head Room Sign	Safemaster	L50	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
198	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
199	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
200	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
201	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
202	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
203	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
204	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
205	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
206	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
207	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
208	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
209	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
210	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
211	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
212	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
213	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
214	Low Pro Anchor Point	Safemaster	L51	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
215	Surfacemount Anchor Point	CARE	L54	Unknown	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Fail	
216	EWP Access Only Sign	Safemaster	L54	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
217	Low Pro Anchor Point	Safemaster	L56	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
218	Low Pro Anchor Point	Safemaster	L56	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
219	Guardrail (AI)	Unknown	L58	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
220	Low Pro Anchor Point	Safemaster	L59	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
221	Low Pro Anchor Point	Safemaster	L59	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
222	Low Pro Anchor Point	Safemaster	L59	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
223	Low Pro Anchor Point	Safemaster	L59	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
224	Low Pro Anchor Point	Safemaster	L59	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
225	Low Head Room Sign	Safemaster	L60	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
226	Low Head Room Sign	Safemaster	L60	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1319	Pass	
227	Access Ladder (Al)	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
228	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
229	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
230	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
231	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
232	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
233	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
234	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
235	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
236	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
237	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
238	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
239	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
240	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
241	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
242	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
243	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
244	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
245	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
246	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
247	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
248	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
249	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
250	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
251	Low Pro Anchor Point	Safemaster	L61	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
252	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
253	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
254	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
255	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
256	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
257	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
258	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
259	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
260	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
261	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
262	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
263	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
264	Low Pro Anchor Point	Safemaster	L62	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Guardrail (Galv)	Unknown	L64	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
266	Step Over (Al)	Safemaster	L67	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
267	Step Over (Al)	Safemaster	L68	29/03/2018	25/06/2019	25/06/2020	AS 1657:2018	Pass	
268	Access Ladder (Al)	Unknown	L69	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
269	Guardrail (Al)	Unknown	L69	Unknown	25/06/2019	25/06/2020	AS 1657:2018	Pass	
270	Low Pro Anchor Point	Safemaster	L70	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	
271	Low Pro Anchor Point	Safemaster	L70	29/03/2018	25/06/2019	25/06/2020	AS/NZS 1891.4:2009	Pass	

AUTHORISED BY: Brandon Vitek

DATE: 25-06-2019

SIGNATURE:

B. Vitek

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

COMPLIANT REQUIREMENTS

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au