

# Roof Safety Report

**Victoria Gardens Shopping  
Centre, VIC 3121**

Prepared By: Safemaster Safety Products  
Date: 29 June 2018

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Victoria Gardens Shopping Centre in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Victoria Gardens Shopping Centre and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: [recertifications@safemaster.net.au](mailto:recertifications@safemaster.net.au)

Signed for and on behalf of Safemaster Safety Products:



**James Townsend (Height Safety Inspector)**

Roof Safety Report for  
**Victoria Gardens Shopping Centre, VIC 3121**

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Victoria Gardens Shopping Centre	Victoria Gardens Shopping Centre, VIC 3121	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

---

**DATE OF INSPECTION**

29-06-2018

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Victoria Gardens Shopping Centre buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

**TESTING INSTRUMENT**

Product: HILTI Tester



# Inspection Log

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
2	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
3	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
4	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
5	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
6	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
7	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
8	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
9	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
10	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
11	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
12	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
14	Surfacemount Anchor Point	CARE	L19-L20	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
15	Surfacemount Anchor Point	CARE	L35	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
16	Surfacemount Anchor Point	CARE	L36	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
17	Surfacemount Anchor Point	CARE	L54	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
18	Surfacemount Anchor Point	CARE	L5	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
19	Surfacemount Anchor Point	CARE	L5	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
20	Surfacemount Anchor Point	CARE	L5	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
21	Surfacemount Anchor Point	CARE	L5	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
22	Surfacemount Anchor Point	CARE	L5	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
23	Surfacemount Anchor Point	CARE	L5	Unknown	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Fail	
24	Access Ladder (Al)	Unknown	L4	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Access Ladder (AI)	Unknown	L11	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
26	Access Ladder (AI)	Unknown	L12	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
27	Guardrail (AI)	Unknown	L12	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
28	Access Ladder (AI)	Unknown	L16	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
29	Guardrail (AI)	Unknown	L16	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
30	Guardrail (AI)	Unknown	L18	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
31	Access Ladder (AI)	Unknown	L23	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
32	Access Ladder (AI)	Unknown	L26	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
33	Access Ladder (AI)	Unknown	L34	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
34	Guardrail (AI)	Unknown	L34	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
35	Roof Access Hatch	Unknown	L35	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
36	Guardrail (AI)	Unknown	L36	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Access Ladder (Al)	Unknown	L38	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
38	Guardrail (Al)	Unknown	L40	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
39	Guardrail (Al)	Unknown	L49	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
40	Guardrail (Al)	Unknown	L58	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
41	Guardrail (Galv)	Unknown	L64	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
42	Access Ladder (Al)	Unknown	L69	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
43	Guardrail (Al)	Unknown	L69	Unknown	13/06/2016	N/A	AS/NZS 1657-2013	Pass	
44	Access Sign	Safemaster	L23	Unknown	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
45	Access Sign	Safemaster	L3 Access Door	Unknown	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
46	Low Pro Anchor Point	Safemaster	L3	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
47	Low Pro Anchor Point	Safemaster	L3	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
48	Low Pro Anchor Point	Safemaster	L9	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Low Pro Anchor Point	Safemaster	L9	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
50	Low Pro Anchor Point	Safemaster	L9	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
51	Low Pro Anchor Point	Safemaster	L9	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
52	Low Pro Anchor Point	Safemaster	L9	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
53	Low Pro Anchor Point	Safemaster	L9	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
54	Low Pro Anchor Point	Safemaster	L9	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
55	Low Pro Anchor Point	Safemaster	L9	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
56	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
57	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
58	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
59	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
60	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
62	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
63	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
64	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
65	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
66	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
67	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
68	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
69	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
70	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
71	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
72	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
74	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
75	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
76	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
77	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
78	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
79	Low Pro Anchor Point	Safemaster	L14	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
80	Low Pro Anchor Point	Safemaster	L17	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
81	Low Pro Anchor Point	Safemaster	L17	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
82	Low Pro Anchor Point	Safemaster	L18	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
83	Low Pro Anchor Point	Safemaster	L18	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
84	Surfacemount Anchor Point	Safemaster	L21	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Surfacemount Anchor Point	Safemaster	L21	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
86	Surfacemount Anchor Point	Safemaster	L21	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
87	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
88	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
89	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
90	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
91	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
92	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
93	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
94	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
95	Low Pro Anchor Point	Safemaster	L37	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
96	Low Pro Anchor Point	Safemaster	L41	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Low Pro Anchor Point	Safemaster	L41	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
98	Low Pro Anchor Point	Safemaster	L41	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
99	Low Pro Anchor Point	Safemaster	L41	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
100	Low Pro Anchor Point	Safemaster	L41	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
101	Surfacemount Anchor Point	Safemaster	L42	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
102	Surfacemount Anchor Point	Safemaster	L42	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
103	Surfacemount Anchor Point	Safemaster	L42	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
104	Surfacemount Anchor Point	Safemaster	L42	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
105	Low Pro Anchor Point	Safemaster	L44	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
106	Low Pro Anchor Point	Safemaster	L44	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
107	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
108	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
110	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
111	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
112	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
113	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
114	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
115	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
116	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
117	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
118	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
119	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
120	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
122	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
123	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
124	Low Pro Anchor Point	Safemaster	L48	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
125	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
126	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
127	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
128	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
129	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
130	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
131	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
132	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
134	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
135	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
136	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
137	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
138	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
139	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
140	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
141	Low Pro Anchor Point	Safemaster	L51	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
142	Low Pro Anchor Point	Safemaster	L56	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
143	Low Pro Anchor Point	Safemaster	L56	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
144	Low Pro Anchor Point	Safemaster	L59	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Low Pro Anchor Point	Safemaster	L59	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
146	Low Pro Anchor Point	Safemaster	L59	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
147	Low Pro Anchor Point	Safemaster	L59	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
148	Low Pro Anchor Point	Safemaster	L59	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
149	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
150	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
151	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
152	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
153	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
154	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
155	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
156	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
157	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
158	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
159	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
160	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
161	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
162	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
163	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
164	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
165	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
166	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
167	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
168	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
170	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
171	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
172	Low Pro Anchor Point	Safemaster	L61	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
173	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
174	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
175	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
176	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
177	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
178	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
179	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
180	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
182	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
183	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
184	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
185	Low Pro Anchor Point	Safemaster	L62	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
186	Low Pro Anchor Point	Safemaster	L70	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
187	Low Pro Anchor Point	Safemaster	L70	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
188	Anchor Point Strop	Safemaster	L41	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1891.4:2009	Pass	
189	EWP Access Only Sign	Safemaster	L1	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
190	EWP Access Only Sign	Safemaster	L2	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
191	EWP Access Only Sign	Safemaster	L39	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
192	EWP Access Only Sign	Safemaster	L54	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
193	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
194	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
195	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
196	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
197	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
198	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
199	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
200	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
201	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
202	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
203	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
204	Brittle Roof Sign	Safemaster	L5	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
205	Brittle Roof Sign	Safemaster	L13	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
206	Brittle Roof Sign	Safemaster	L13	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
207	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
208	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
209	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
210	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
211	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
212	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
213	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
214	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
215	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
216	Brittle Roof Sign	Safemaster	L15	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
217	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
218	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
219	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
220	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
221	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
222	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
223	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
224	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
225	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
226	Brittle Roof Sign	Safemaster	L19 & L20	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
227	Low Head Room Sign	Safemaster	L50	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
228	Low Head Room Sign	Safemaster	L50	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Low Head Room Sign	Safemaster	L60	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
230	Low Head Room Sign	Safemaster	L60	29/03/2018	29/06/2018	29/06/2019	AS/NZS 1319	Pass	
231	Step Over (AI)	Safemaster	L7	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
232	Access Ladder (AI)	Safemaster	L8	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
233	Handrail (AI)	Safemaster	L8	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
234	Access Ladder (AI)	Safemaster	L10	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
235	Handrail (AI)	Safemaster	L10	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
236	Access Ladder (AI)	Safemaster	L22	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
237	Handrail (AI)	Safemaster	L22	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
238	Step Over (AI)	Safemaster	L24	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
239	Step Over (AI)	Safemaster	L24	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
240	Step Over (AI)	Safemaster	L25	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
241	Step Over (AI)	Safemaster	L25	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
242	Step Over (AI)	Safemaster	L27	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
243	Step Over (AI)	Safemaster	L27	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
244	Handrail (AI)	Safemaster	L29	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
245	Access Ladder (AI)	Safemaster	L30	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
246	Handrail (AI)	Safemaster	L30	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
247	Handrail (AI)	Safemaster	L31	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
248	Handrail (AI)	Safemaster	L32	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
249	Handrail (AI)	Safemaster	L33	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
250	Step Over (AI)	Safemaster	L34	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
251	Access Ladder (AI)	Safemaster	L41	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
252	Access Ladder (AI)	Safemaster	L43	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

**Client:** Vicinity Centres

**Job Ref:** SM12182


**Site:** Victoria Gardens Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
253	Handrail (AI)	Safemaster	L43	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
254	Step Over (AI)	Safemaster	L43	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
255	Access Ladder (AI)	Safemaster	L46	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
256	Handrail (AI)	Safemaster	L46	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
257	Access Ladder (AI)	Safemaster	L46	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
258	Access Ladder (AI)	Safemaster	L47	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
259	Handrail (AI)	Safemaster	L47	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
260	Access Ladder (AI)	Safemaster	L61	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
261	Step Over (AI)	Safemaster	L67	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	
262	Step Over (AI)	Safemaster	L68	29/03/2018	29/06/2018	N/A	AS/NZS 1657-2013	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 29/06/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## COMPLIANT REQUIREMENTS

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)