

Roof Safety Report

Vueze Apartments

Prepared By: Safemaster Safety Products
Date: 15/01/2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Vueze Apartments in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Vueze Apartments and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Brandon Vitek (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Brandon Vitek (Height Safety Inspector)

Roof Safety Report for
Vueze Apartments

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Logiudice	Vueze Apartments	Anchor Points Signage Hatch Ladder

DATE OF INSPECTION

15/01/2019

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Vueze Apartments buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Logiudice

Job Ref: SM 10369

Site: Vueze Apartments

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
12	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Logiudice

Job Ref: SM 10369

Site: Vueze Apartments

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point Abseil 15 kN	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1891.4:2009	Pass	
22	Pull Down Ladder	Unknown	Main Roof	Unknown	15/01/2019	15/01/2020	AS1691:2013	Fail	Fall risk at side of ladder into stair well
23	Pull Down Ladder	Unknown	Main Roof	Unknown	15/01/2019	15/01/2020	AS1691:2013	Fail	Fall risk at side of ladder into stair well
24	Hatch	Unknown	Main Roof	Unknown	15/01/2019	15/01/2020	AS1691:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Logiudice

Job Ref: SM 10369

Site: Vueze Apartments

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Hatch	Unknown	Main Roof	Unknown	15/01/2019	15/01/2020	AS1691:2013	Pass	
26	Access Sign	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1319:1994 AS1891.4-2009	Pass	
27	Access Sign	SRE	Main Roof	1/07/2009	15/01/2019	15/01/2020	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: BRANDON VITEK

DATE: 15/01/2019

SIGNATURE: 

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au