

# Roof Safety Report

Warwick Police Station

Prepared By: Safemaster Safety Products  
Date: 27/04/2018

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Warwick Police Station in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Warwick Police Station and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tyron Menikides (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Tyron Menikides (Height Safety Inspector)**

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Western Australia Police Force	Warwick Police Station	Anchor Points Signage Ladder Bracket Hatch Strop

---

**DATE OF INSPECTION**

20/04/2018

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Warwick Police Station building.

The inspection is based on:

- Work Health and Safety Regulations 2012
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

**TESTING INSTRUMENT**

Product: N/A



Inspection Log

# CERTIFICATE OF COMPLIANCE

33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Western Australia Police Force

**Job Ref:** SM13291

**Site:** Warwick Police Station

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Sign	Safemaster/ Safemaster	Lower Roof	2/05/2017	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
2	Ladder Access Bracket	Safemaster/ Safemaster	Lower Roof	2/05/2017	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
3	Access Strop -15kN	Safemaster/ Safemaster	Lower Roof	29/05/2012	29/05/2012	20/10/2018	AS1891.4:2009	Pass	In Working Order
4	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
5	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
6	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
7	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
8	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
9	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
10	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
11	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
12	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Western Australia Police Force

**Job Ref:** SM13291

**Site:** Warwick Police Station

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
14	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
15	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
16	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
17	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
18	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
19	Anchor Point-Surface Mount-15kN	RIS/RIS	Lower Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
20	Sign	RIS/RIS	Upper Roof	2/05/2017	20/04/2018	20/10/2018	AS1319:1994 AS1891.4:2009	Pass	Legible
21	Hatch	Unknown	Upper Roof	2018	20/04/2018	20/10/2018	N/A	Pass	In Working Order
22	Access Strop -15kN	Safemaster/ Safemaster	Upper Roof	29/05/2012	29/05/2012	20/10/2018	AS1891.4:2009	Pass	In Working Order
23	Vertical Ladder With Static Line	RIS/RIS	Upper Roof	Unknown	20/04/2018	20/10/2018	AS1657:1997 AS1891.4:2009	Pass	In Working Order
24	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Western Australia Police Force

**Job Ref:** SM13291

**Site:** Warwick Police Station

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
26	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
27	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
28	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
29	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
30	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
31	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
32	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
33	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
34	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
35	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order
36	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Western Australia Police Force

**Job Ref:** SM13291

**Site:** Warwick Police Station

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Anchor Point-Surface Mount-15kN	RIS/RIS	Upper Roof	29/05/2012	20/04/2018	20/10/2018	AS1891.4:2009	Pass	In Working Order

AUTHORISED BY TYRON MENIKIDES

DATE: 20/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## Roof Safety Report for Warwick Police Station

## COMPLIANT REQUIREMENTS

[illegible]



**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6218 5158

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)