

Roof Safety Report

**Yongah Immigration Detention
Centre**

Prepared By: Safemaster Safety Products
Date: 18/12/2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Yongah Hill IDC in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Serco and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tony Pennington (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Tony Pennington (Height Safety Inspector)

Roof Safety Report for
Yongah Immigration Detention Centre

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Serco	Yongah Hill IDC	Anchor Points Signage Ladder Brackets

DATE OF INSPECTION

17/12/2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Yongah Hill IDC buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Sign	Safemaster / Safemaster	01.15	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Pass	
2	Ladder Bracket	Safemaster / Safemaster	01.15	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
3	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.15	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
4	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.15	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
5	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.15	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
6	Sign	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Pass	
7	Ladder Bracket	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
8	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
9	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
10	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
11	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
12	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
13	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
14	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
15	Sign	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Pass	
16	Ladder Bracket	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
17	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
18	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
19	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
20	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
21	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
22	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
23	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
24	Sign	Safemaster / Safemaster	01.30	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
25	Ladder Bracket	Safemaster / Safemaster	01.30	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
26	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.30	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
27	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.30	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
28	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.30	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
29	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.30	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
30	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.30	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
31	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.30	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
32	Sign	Safemaster / Safemaster	01.29	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
33	Ladder Bracket	Safemaster / Safemaster	01.29	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
34	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.29	Year 2017	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
35	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.29	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
36	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.29	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
37	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.29	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
38	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.29	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
39	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.29	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
40	Sign	Safemaster / Safemaster	01.31	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4:2009	Pass	
41	Ladder Bracket	Safemaster / Safemaster	01.31	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
42	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.31	Year 2017	17/12/2019	17/06/2020	AS1891.4:2009	Non-Compliant	Strop (1100mm) required.
43	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.31	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
44	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.31	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
45	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.31	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
46	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.31	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
47	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.31	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
48	Ladder Bracket	Safemaster / Safemaster	01.27	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	Sign required at access point.
49	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.27	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
50	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.27	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
51	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.27	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
52	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.27	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
53	Sign	Safemaster / Safemaster	01.28	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
54	Ladder Bracket	Safemaster / Safemaster	01.28	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
55	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.28	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
56	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.28	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
57	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.28	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
58	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.28	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
59	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.28	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
60	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.28	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
61	Sign	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
62	Ladder Bracket	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
63	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
64	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
65	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
66	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
67	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
68	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
69	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.26	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
70	Sign	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
71	Ladder Bracket	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
72	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
73	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
74	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
75	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
76	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
77	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
78	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
79	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
80	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
81	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
82	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.18	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires sign, ladder bracket, strop & anchors.
83	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.18	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires sign, ladder bracket, strop & anchors.
84	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.18	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires sign, ladder bracket, strop & anchors.
85	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.18	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires sign, ladder bracket, strop & anchors.
86	Sign	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
87	Ladder Bracket	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
88	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
89	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
90	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
91	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
92	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
93	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
94	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
95	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
96	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
97	Sign	Safemaster / Safemaster	Car Park Healthcare	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
98	Ladder Bracket	Safemaster / Safemaster	Car Park Healthcare	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
99	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Car Park Healthcare	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
100	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Car Park Healthcare	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
101	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Car Park Healthcare	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
102	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Car Park Healthcare	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
103	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Car Park Healthcare	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
104	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Car Park Healthcare	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
105	Sign	Safemaster / Safemaster	04.08	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
106	Ladder Bracket	Safemaster / Safemaster	04.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
107	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
108	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
109	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
110	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
111	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
112	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.08	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
113	Sign	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
114	Ladder Bracket	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
115	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
116	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
117	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
118	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
119	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
120	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
121	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
122	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
123	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14 - Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (2m approx) including additional anchors
124	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14 - Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (2m approx) including additional anchors
125	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.14 - Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (2m approx) including additional anchors
126	Sign	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
127	Ladder Bracket	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
128	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
129	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
130	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
131	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
132	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
133	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
134	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
135	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
136	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Western Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
137	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Western Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
138	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Access From 04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	Safer access required. Recommend handrail on walkway connecting 04.13 to 04.14.
139	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Access From 04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	Safer access required. Recommend handrail on walkway connecting 04.13 to 04.14.
140	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Access From 04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	Safer access required. Recommend handrail on walkway connecting 04.13 to 04.14.
141	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Access From 04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	Safer access required. Recommend handrail on walkway connecting 04.13 to 04.14.

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
142	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Access From 04.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	Safer access required. Recommend handrail on walkway connecting 04.13 to 04.14.
143	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Eastern Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Recommend ladder (4m approx) to access.
144	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Eastern Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Recommend ladder (4m approx) to access.
145	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Eastern Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Recommend ladder (4m approx) to access.
146	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.13 - Eastern Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Recommend ladder (4m approx) to access.
147	Sign	Safemaster / Safemaster	04.02	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
148	Ladder Bracket	Safemaster / Safemaster	04.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
149	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
150	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
151	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
152	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
153	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
154	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Sign	Safemaster / Safemaster	04.01	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
156	Ladder Bracket	Safemaster / Safemaster	04.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
157	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Non-Compliant	Requires a strop (1.5m)
158	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
159	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
160	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
161	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
162	Sign	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
163	Ladder Bracket	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
164	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
165	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
166	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
167	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
168	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
169	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
170	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
171	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
172	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
173	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
174	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
175	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.04	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
176	Sign	Safemaster / Safemaster	04.10	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
177	Ladder Bracket	Safemaster / Safemaster	04.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
178	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
179	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
180	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
182	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.10-Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Recommend ladder (1.3m approx) to access.
183	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.10-Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Recommend ladder (1.3m approx) to access.
184	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.10-Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Recommend ladder (1.3m approx) to access.
185	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	04.10-Raised Section	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Recommend ladder (1.3m approx) to access.
186	Sign	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
187	Ladder Bracket	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
188	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
189	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
190	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
191	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
192	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
193	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
194	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
195	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
196	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
197	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Ladder (4m approx) required.
198	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Ladder (4m approx) required.
199	Sign	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
200	Ladder Bracket	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
201	Access Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
202	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
203	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
204	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
205	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
206	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
207	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
208	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
209	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
210	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
211	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
212	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
213	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	03.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
214	Sign	Safemaster / Safemaster	02.03	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
215	Ladder Bracket	Safemaster / Safemaster	02.03	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
216	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.03	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
217	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.03	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
218	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.03	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
219	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.03	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
220	Sign	Safemaster / Safemaster	Bin Waste	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4:2009	Fail	Sign Needs Replacing
221	Ladder Bracket	Safemaster / Safemaster	Bin Waste	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
222	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Bin Waste	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
223	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Bin Waste	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
224	Sign	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4:2009	Fail	Sign Needs Replacing
225	Ladder Bracket	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
226	Access Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Fail	Too much movement in anchor. Purlin possibly compromised
227	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
228	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
229	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
230	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
231	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
232	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
233	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
234	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
235	Access Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
236	Sign	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
237	Ladder Bracket	Safemaster / Safemaster	04.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
238	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.20	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
239	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.20	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
240	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.20	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
241	Sign	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
242	Ladder Bracket	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
243	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Non-Compliant	Requires relocation to be next to the ladder bracket.
244	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
245	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
246	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
247	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
248	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
249	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
250	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
251	Sign	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
252	Ladder Bracket	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
253	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
254	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
255	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
256	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
257	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
258	Ladder Bracket	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	Requires sign.

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
259	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Non-Compliant	Requires strop (1.3m approx).
260	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
261	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.16	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
262	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
263	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
264	Sign	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
265	Ladder Bracket	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
266	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
267	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
268	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
269	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
270	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
271	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
272	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
273	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
274	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
275	Sign	Safemaster / Safemaster	03.12	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
276	Ladder Bracket	Safemaster / Safemaster	03.12	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
277	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.12	Year 2017	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
278	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.12	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
279	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.12	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
280	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.12	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
281	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.12	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
282	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
283	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
284	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
285	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	03.14	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
286	Sign	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
287	Ladder Bracket	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	Requires anchor and strop(1.1m approx).
288	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
289	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
290	Sign	Safemaster / Safemaster	Sallyport	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Not Inspected	No Safe Access. Requires ladder (3m approx) from building 02.01.
291	Ladder Bracket	Safemaster / Safemaster	Sallyport	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (3m approx) from building 02.01.
292	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Sallyport	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (3m approx) from building 02.01.
293	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Sallyport	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (3m approx) from building 02.01.
294	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Sallyport	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (3m approx) from building 02.01.
295	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Sallyport	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (3m approx) from building 02.01.
296	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Sallyport	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (3m approx) from building 02.01.
297	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Sallyport	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Not Inspected	No Safe Access. Requires ladder (3m approx) from building 02.01.

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
298	Sign	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4:2009	Fail	Sign Needs Replacing
299	Ladder Bracket	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
300	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
301	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
302	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
303	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
304	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
305	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
306	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	02.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
307	Sign	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4:2009	Pass	
308	Ladder Bracket	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
309	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
310	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
311	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
312	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
313	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
314	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
315	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
316	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
317	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.01	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
318	Sign	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Pass	
319	Ladder Bracket	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
320	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
321	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
322	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
323	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
324	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
325	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
326	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
327	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
328	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
329	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
330	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.23	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
331	Sign	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Pass	
332	Ladder Bracket	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
333	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
334	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
335	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
336	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
337	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
338	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
339	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
340	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
341	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	01.02	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
342	Sign	Safemaster / Safemaster	1.20	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
343	Ladder Bracket	Safemaster / Safemaster	1.20	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
344	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	1.20	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
345	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	1.20	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
346	Sign	Safemaster / Safemaster	2.06	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
347	Ladder Bracket	Safemaster / Safemaster	2.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
348	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
349	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
350	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
351	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.06	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
352	Sign	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
353	Ladder Bracket	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
354	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
355	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
356	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
357	Sign	Safemaster / Safemaster	2.10	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
358	Ladder Bracket	Safemaster / Safemaster	2.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
359	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
360	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
361	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
362	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.10	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
363	Sign	Safemaster / Safemaster	2.05	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
364	Ladder Bracket	Safemaster / Safemaster	2.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
365	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
366	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
367	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
368	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.05	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
369	Sign	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
370	Ladder Bracket	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
371	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
372	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
373	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.09	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
374	Sign	Safemaster / Safemaster	2.11	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
375	Ladder Bracket	Safemaster / Safemaster	2.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
376	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
377	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
378	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.11	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
379	Sign	Safemaster / Safemaster	2.07	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
380	Ladder Bracket	Safemaster / Safemaster	2.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
381	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
382	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
383	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
384	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.07	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
385	Sign	Safemaster / Safemaster	2.12	1/05/2012	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	Sign Needs Replacing
386	Ladder Bracket	Safemaster / Safemaster	2.12	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
387	Access Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.12	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
388	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	2.12	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
389	Sign	Safemaster / Safemaster	Hign Security Office	1/06/2018	17/12/2019	17/06/2020	AS1319:1994 AS1891.4-2009	Fail	
390	Ladder Bracket	Safemaster / Safemaster	Hign Security Office	1/06/2018	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
391	Access Strop Line	Safemaster / Safemaster	Hign Security Office	1/06/2018	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
392	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Office	1/06/2018	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
393	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Office	1/06/2018	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
394	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Office	1/06/2018	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
395	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Office	1/06/2018	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
396	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
397	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
398	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
399	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
400	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
401	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Serco
Job Ref: SM7105
Site: Yongah Hill Immigration Detention Centre

Item No	Equipment Type & Description	Manufacturer / Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
402	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
403	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
404	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
405	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
406	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
407	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
408	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
409	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	
410	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	Hign Security Walkway	1/05/2012	17/12/2019	17/06/2020	AS1891.4:2009	Pass	

AUTHORISED BY: Tony Pennington

DATE: 18/12/2019

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Compliance Requirements

Item No	Location	Recommendations
24	01.30	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
32	01.29	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
40	01.31	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
42	01.31	1100mm strop is required to allow safe access to the roof.
48	01.27	Sign required at access point.
53	01.28	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
61	01.26	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
70	01.06	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
82 to 85	04.18	Requires sign, ladder bracket, strop & additional anchors to allow safe access to the roof.
86	04.07	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
97	Car Park Healthcare	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
105	04.08	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
113	04.14	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
123 to 125	04.14 - Raised Section	Requires ladder (2m approx) including additional anchors to allow safe access to area.
126	04.13	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
138 to 142	04.13 - Access From 04.14	Recommend handrail on walkway roof connecting 04.13 to 04.14.
143 to 146	04.13 - Eastern Raised Section	Recommend ladder (4m approx) to allow safe access the upper roof.
147	04.02	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
155	04.01	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
157	04.01	1500mm strop is required to allow safe access to the roof.
162	04.04	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
176	04.10	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
182 to 185	04.10-Raised Section	Recommend ladder (1.3m approx) to allow safe access the upper roof.
186	03.06	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
197 & 198	03.06	Recommend ladder (4m approx) to allow safe access the upper roof.
199	03.09	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
214	02.03	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.

Roof Safety Report for
Yongah Immigration Detention Centre

220	Bin Waste	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
224	04.11	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
226	04.11	Anchor to be relocated.
236	04.11	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
241	03.02	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
243	03.02	Requires relocation to be next to the ladder bracket to allow safe access to the roof.
251	03.16	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
258	03.16	Sign required at access point.
259	03.16	1300mm strop is required to allow safe access to the roof.
264	03.05	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
275	03.12	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
286	01.02	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
287	01.02	1100mm strop is required to allow safe access to the roof.
290 to 297	Sallyport	Requires ladder (3m approx) from building 02.01.
298	02.01	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
342	1.20	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
346	2.06	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
352	2.09	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
357	2.10	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
363	2.05	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
369	2.09	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
379	2.07	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.
385	2.12	Sign is weathered and non-legible. Sign is required to be replaced before the system is used.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au