

Roof Safety Report

**Corio Central Shopping Centre,
VIC 3214**

Prepared By: Safemaster Safety Products
Date: 06-12-2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Corio Central Shopping Centre, VIC in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Corio Central Shopping Centre, VIC and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



James Townsend (Recertification Technician)

Roof Safety Report for
Corio Central Shopping Centre, VIC 3214

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres - Corio Central Shopping Centre	Corner Bacchus Marsh and Purnell Roads, Corio VIC 3214	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

02-12-2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Corio Central Shopping Centre.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester





Inspection Log



Roof Safety Report for
Corio Central Shopping Centre, VIC 3214

ADDITIONAL FINDINGS & RECOMMENDATIONS



Table below summarises additional findings and recommendations in support of the Roof Safety Report.

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Current Risk Level	Proposed Permanent Solution	Residual Risk Assessment	Details of Action Taken	Status	Reference
115	Building: General Stores Location Reference: L01 Task: Access to the A/c units									
		No safe access to the A/c units	Trips, Slips and Falls	N/A	Low	Supply walkway to the A/c units	Low	Client advised	Outstanding	-
116	Building: General Stores Location Reference: L04 Task: Access to the roof									
		Duct installed over the walkway path	Trips, Slips and Falls	Awareness induction	Med	Additional walkway sections to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7



Roof Safety Report for
Corio Central Shopping Centre, VIC 3214

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
117	<p>Building: General Stores Location Reference: L1 Task: Restrict access to the roof</p> 	No height safety system installed	Trips, Slips and Falls	Restrict Access	High	EWP Access Only sign to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55 & 3.11
118	<p>Building: General Stores Location Reference: L56 Task: Access to the A/c units</p> 	No safe access to the A/c units	Trips, Slips and Falls	N/A	Low	Supply walkway to the A/c units	Low	Client advised	Outstanding	-

Roof Safety Report for
Corio Central Shopping Centre, VIC 3214

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
119	Building: General Stores Location Reference: L55 Task: Access to the A/c units									
		No safe access to the A/c units	Trips, Slips and Falls	N/A	Low	Supply walkway to the A/c units	Low	Client advised	Outstanding	-
120	Building: General Stores Location Reference: L41 Task: Access to the roof									
		Handrail is missing for plant deck	Trips, Slips and Falls	Awareness induction	Med	Handrail to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7 AS/NZS 1657-2013 4.4

Roof Safety Report for
Corio Central Shopping Centre, VIC 3214

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
121	Building: General Stores Location Reference: L41 Task: Access to the roof									
		Gap between plant deck and unit is greater than required maximum	Trips, Slips and Falls	Awareness induction	Med	Gap to be closed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7 AS/NZS 1657-2018 3.2.3.4
122	Building: General Stores Location Reference: L26 Task: Access to the A/c units									
		No safe access to the A/c units	Trips, Slips and Falls	N/A	Low	Supply walkway to the A/c units	Low	Client advised	Outstanding	-

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
2	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
3	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
5	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
6	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
7	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
11	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Woolworths Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
13	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
14	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
15	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
16	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
17	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
18	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
19	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
20	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
21	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
22	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
24	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
25	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
26	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
27	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
28	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
30	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
31	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
32	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
33	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
35	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
36	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
37	Surfacemount Anchor Point 15 kN	Advanced Height Safety	Reject shop Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
38	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
39	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
40	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
41	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
42	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
43	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
44	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
46	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
47	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
48	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
49	Surfacemount Anchor Point 15 kN	Tech Line	Coles Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
50	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
51	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
52	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
53	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
54	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
55	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
57	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
58	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
59	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
60	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
61	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
62	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
63	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
64	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
65	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
66	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
68	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
69	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
70	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
71	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
72	Low Pro Anchor Point 15 kN	Advanced Height Safety	Centrelink Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
73	Horizontal Static Line 21 kN	Tech Line	Mall Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
74	Horizontal Static Line 21 kN	Tech Line	Mall Roof	18/01/2017	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
75	Surfacemount Anchor Point 15 kN	Tech Line	Plant Room Roof	1/07/2014	2/12/2019	2/12/2020	AS1891.4:2009	Pass	
76	Access Ladder (AI)	Unknown	L1	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
77	Handrail (AI)	Unknown	L1	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Access Ladder (Al)	Unknown	L3	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
79	Handrail (Al)	Unknown	L3	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
80	Step (Al)	Unknown	L4	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
81	Access Stair (Galv)	Unknown	L6	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
82	Access Ladder (Al)	Unknown	L7	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
83	Access Ladder (Al)	Unknown	L7	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
84	Access Ladder (Al)	Unknown	L7	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
85	Access Ladder (Al)	Unknown	L7	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
86	Handrail (Al)	Unknown	L7	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
87	Access Stair (Al)	Unknown	L8	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
88	Access Stair (Galv)	Unknown	L10	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Handrail (Galv)	Unknown	L10	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
90	Access Stair (Galv)	Unknown	L11	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
91	Handrail (Galv)	Unknown	L11	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
92	Access Stair (Al)	Unknown	L12	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
93	Access Ladder (Galv)	Unknown	L12	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
94	Access Ladder (Galv)	Unknown	L13	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
95	Access Ladder (Galv)	Unknown	L16	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
96	Access Ladder (Galv)	Unknown	L16	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
97	Handrail (Al)	Unknown	L17	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
98	Access Ladder (Galv)	Unknown	L17	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
99	Step (Al)	Unknown	L17	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Access Ladder (Galv)	Unknown	L17	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
101	Access Ladder (Galv)	Unknown	L18	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
102	Handrail (Al)	Unknown	L18	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
103	Access Stair (Al)	Unknown	L22	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
104	Access Stair (Al)	Unknown	L23	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
105	Access Stair (Al)	Unknown	L23	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
106	Handrail (Al)	Unknown	L23	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
107	Access Ladder (Al)	Unknown	L26	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
108	Handrail (Al)	Unknown	L26	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
109	Handrail (Galv)	Unknown	L26	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
110	Access Stair (Al)	Unknown	L26	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Handrail (AI)	Unknown	L28	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
112	Access Ladder (AI)	Unknown	L31	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
113	Step (AI)	Unknown	L33	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
114	Step (AI)	Unknown	L35	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
115	Access Ladder (AI)	Unknown	L35	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
116	Access Ladder (AI)	Unknown	L36	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
117	Access Ladder (AI)	Unknown	L39	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
118	Handrail (AI)	Unknown	L39	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
119	Access Ladder (AI)	Unknown	L40	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
120	Handrail (AI)	Unknown	L40	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
121	Step (AI)	Unknown	L41	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Handrail (AI)	Unknown	L41	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
123	Step (AI)	Unknown	L42	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
124	Handrail (AI)	Unknown	L42	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
125	Access Ladder (AI)	Unknown	L44	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
126	Access Ladder (AI)	Unknown	L44	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
127	Handrail (AI)	Unknown	L44	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
128	Handrail (AI)	Unknown	L50	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
129	Step (AI)	Unknown	L50	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
130	Access Ladder (AI)	Unknown	L52	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
131	Access Ladder (AI)	Unknown	L54	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Pass	
132	Handrail (AI)	Unknown	L54	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Access Ladder (AI)	Unknown	L55	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
134	Handrail (AI)	Unknown	L55	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
135	Handrail (AI)	Unknown	L56	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
136	Step (AI)	Unknown	L58	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
137	Access Ladder (AI)	Unknown	L58	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
138	Step (AI)	Unknown	L58	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
139	Step (AI)	Unknown	L58	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
140	Step (AI)	Unknown	L58	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
141	Step (AI)	Unknown	L58	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	
142	Handrail (AI)	Unknown	L58	1/07/2014	2/12/2019	2/12/2020	AS1657:2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Corio Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
---------	-----------------------------	-------------------------	----------	-----------------	-----------	----------------	---------------------	--------	----------

AUTHORISED BY: JAMES TOWNSEND

DATE: 02-12-2019

SIGNATURE:





Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au